

Brad Stangohr PE

©2020 Ulteig

- » All bridges South of 190th St. (64 bridges total)
- » This year's findings General
- » This year's findings Key Findings
- » Key repair and replacement recommendations
- » Options for the way forward
- » GIS


- » Legal Load Carrying Capacity reduced on 3 bridges
- » Major repairs needed on 6 bridges
- » Program for replacement recommended on 6 bridges

- » Legal Load Carrying Capacity changed on 3 bridges
 - Bridge Number 30-030-345 (Steel Stringer/Timber Deck) reduced from 25-42 to 23-39
 - Bridge Number 30-250-208 (Concrete Slab Bridge) Increased from 26-43 to 30-Legal
 - Bridge Number 30-280-198 (Double Tee/Timber Abut) reduced from Legal to 10-10 until repairs are made.

- » Major Repairs Recommended on 6 bridges
 - Bridge Number 30-154-258 (Concrete Arch) Historical Bridge BIG Rehab Grant Repair Concrete Substructure
 - Bridge Number 30-170-197 (Double Tee/Timber Abut) Undermining of timber backwall has caused the roadway to collapse, riprap abutment and backfill roadway.
 - Bridge Number 30-280-198 (Double Tee/Timber Abut) Ice damage to piles, place concrete collars around piles.


- » Major Repairs Recommended on 6 bridges (Cont.)
 - Bridge Number 30-250-189 (Concrete Slab) Undermined Abutments- Place flowable fill under abutments and place fabric/riprap on berm slopes.
 - Bridge Number 30-250-194 (Concrete Slab) Undermined Abutments- Place fabric/riprap on berm slopes.
 - Bridge Number 30-250-208 (Concrete Slab) Undermined Abutments- Place flowable fill under abutments and place fabric/riprap on berm slopes.

- » Major Repairs Recommended on 6 bridges (Cont.)
 - Bridge Number 30-154-258 (Concrete Arch) Historical Bridge BIG Rehab Grant Repair Concrete Substructure










- » Major Repairs Recommended on 6 bridges (Cont.)
 - Bridge Number 30-170-197 (Double Tee/Timber Abut) Undermining of timber backwall has caused the roadway to collapse, riprap abutment and backfill roadway.




©2020 Ulteig







- » Major Repairs Recommended on 6 bridges
 - Bridge Number 30-280-198 (Double Tee/Timber Abut) Ice damage to piles, place concrete collars around piles.



©2020 Ulteig










- » Major Repairs Recommended on 6 bridges (Cont.)
 - Bridge Number 30-250-189 (Concrete Slab) Undermined Abutments- Place flowable fill under abutments and place fabric/riprap on berm slopes.
 - Bridge Number 30-250-194 (Concrete Slab) Undermined Abutments- Place fabric/riprap on berm slopes.
 - Bridge Number 30-250-208 (Concrete Slab) Undermined Abutments- Place flowable fill under abutments and place fabric/riprap on berm slopes.
















- » Replacement Recommended on 5 bridges
 - Bridge Number 30-170-185 (Pony Truss) Ice damage to gusset plates and pack rust, #2 priority.
 - Bridge Number 30-194-250 (Pony Truss) Damaged truss members from traffic impacts. # 5 priority.
 - Bridge Number 30-220-256 (Steel Stringer) Corner of abutment is settling, #1 priority.


- » Replacement Recommended on 5 bridges (Cont.)
 - Bridge Number 30-240-188 (Steel Stringer) South Abutment has large cracks and the SW wingwall is tipping and heavily cracked. #4 priority
 - Bridge Number 30-250-412 (Steel Stringer) SW Wingwall with, deck unit on top, is cracked and tilting and settling. #3 priority



©2020 Ulteig


Ulteig





















©2020 Ulteig









©2020 Ulteig

Ulteig









©2020 Ulteig



2020 Bridge Safety Inspections

- » Options for the way forward
- » 2-Replacements/Year
- » SDDOT BIG Program 80%-20% Match
 - Bridge must serve multiple residences.
 - Must have a DOT approved 5-year plan.
 - Must have a wheel tax. (Points = actual amount x 2, max 10)
 - BIG PE Covers preliminary engineering costs
 - BIG Replacement/Rehab Covers construction costs

2020 Bridge Safety Inspections

» Questions???????



2020 Bridge Safety Inspections

» GIS Demonstration

